

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton **Division Director**

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)



INSPECTION REPORT

Partial 2	XXX Complete	Exploration
Inspection Date:	06/20/2002/ Time:	10:00am-2:00pm
	Date of Last Inspec	

Mine Name: <u>Deer Creek Mine</u>	County: Emery	Permit Number: <u>C/015/018</u>					
Permittee and/or Operator's Name: PacifiCorp							
Business Address: P.O. Box 310, Huntington, Utah 84528							
Company Official(s): Dennis Oakley							
State Official(s): Stephen J. Demczak Federal Official(s): None							
Weather Conditions: Warm, Sunny, 80's							
Type of Mining Activity: Underground XX	X Surface Prep	PlantOther					
Existing Acreage: Permitted 19010 Distu	rbed <u>95.79</u> Regr	aded Seeded					
Status: Active							

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	
2.	SIGNS AND MARKERS	\Box			\Box
3.	TOPSOIL				
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	
b	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	
d.	WATER MONITORING	[X]		[X]	
e.	EFFLUENT LIMITATIONS	Ĺĺ			[]
5.	EXPLOSIVES				
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES				
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]		[X] [X]	
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION				[_]
12.	BACKFILLING AND GRADING				
13.	REVEGETATION			\Box	
14.	SUBSIDENCE CONTROL				
15.	CESSATION OF OPERATIONS	· [_]			. []
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES				Ļ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]		[X]	
19.	AVS CHECK (4th Quarter- April, May, June)	· []			ГŢ
20.	AIR QUALITY PERMIT				Ļ
21.	BONDING & INSURANCE				

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/018</u>

DATE OF INSPECTION: 06/20/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has the following permitting action for review at the Division. These are a) Mill Fork Lease, b) Revision to Reclamation Plan, c) Volume 1, General Content, and d) Permit area Change (66.7 acres)

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and complied with the requirements in the Mining and Reclamation Plan. These diversions met the R645 performance standards.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site sediment pond was discharging during the inspection. There were no signs of hazardous conditions. The sediment pond in July is scheduled to be cleaned. The refuse sediment pond was also inspected with no signs of hazardous conditions existing. This sediment pond did not contain water and is unlikely to discharge in the near future.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The catch basins were constructed as designed. No water was within these structures.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has been entering water sampling information in to the Electronic Data Base.

The permittee has been notified that in the future the Division will not accept "No Access" to a water-monitoring site as meeting their water monitoring requirements.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The refuse piles were inspected and no hazardous conditions were noticed.

8. NONCOAL WASTE

The disturbed area at the mine is generally clear of non-coal waste material.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new construction at the mine had taken place.

Inspector's Signature:

Date: July 5, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM

Chuck Semborski, PacifiCorp

Price Field office

O:\015018.DER\Compliance\2002\p_0620.doc